


**CAD-DRAWING**  
 THIS DRAWING WAS CREATED ON  
 A COMPUTER AIDED DESIGN ( CAD )  
 SYSTEM. TO INSURE THE INTEGRITY  
 OF THE DATA BASE, ALL CHANGES/  
 REVISIONS MUST BE MADE ON THE  
 CAD SYSTEM.

REVISION	DATE
A	02/22/16


**TOOLS REQUIRED:**



PERSONAL PROTECTIVE  
EQUIPMENT (PPE)

**MATERIAL TYPE:**

- ① STEEL
- ② ALUMINUM
- ③ FABRIC
- ④ PLASTIC
- ⑤ GLASS
- ⑥ FIBERGLASS
- ⑦ FIBERBOARD
- ⑧ WOOD



PROCEDURE:

- 1) REMOVE T-MOLDING.

GENERAL NOTES:

- 1) DISASSEMBLY TIME 5-10 MINUTES
- 2) THIS PROCEDURE ASSUMES BASIC FAMILIARITY WITH HAND TOOLS AND FURNITURE TERMINOLOGY: NO SPECIALIZED TRAINING IS REQUIRED.
- 3) ALL MATERIAL REMOVED AND DISASSEMBLED SHALL BE SORTED AND SEGREGATED WITH LIKE MATERIALS AND DISPOSED OF OR RECYCLED ACCORDING TO RECYCLING AVAILABILITY OR WASTE ACCEPTANCE.
- 4) FOR ITEMS TO BE RECYCLED, REFER TO CALPIA WEBSITE AT WWW.CALPIA.CA.GOV.

CALPIA  
 STATE OF CALIFORNIA, PRISON INDUSTRY AUTHORITY  
 560 EAST NATOMA STREET, FOLSOM, CALIFORNIA, 95630

CENTURY SYSTEMS  
 DISASSEMBLY INSTRUCTIONS AND RECYCLING CONTENT  
 WORK SURFACE

DRAWN BY: D. SPIVEY	DRAWN DATE: 02/22/16	SIZE: D	SCALE: NTS	DWG NO.: 6700-8A-DR
---------------------	----------------------	---------	------------	---------------------